HSC 2002 - Industrial Technology

Evidence of Solutions to Problems in Production

Demonstrates solutions to one or two simple problems.

PROBLEMS

- First problem was the time I purchased and transported the wood. It took two weeks to transport all my wood.
- Next was the wood. Some was warped, especially the desktop. When I joined them together the tabletop was warped. Planning it made it level yet left the desktop at different thicknesses.
- The top piece was too short for my desk frame so I had to add pieces of wood to the front and back and added pieces to the sides to hide the desk frame.
- Final problem was the drawers. At first they
 were a few millimetres too big. Then after
 everything was put together they needed more
 sanding. Wax had to be applied to the edges of
 the drawers and runners to give it a smooth run.