

HSC 2002 – Industrial Technology

Evidence of Safe Working Practices and OH&S Issues

Band 3/4

Demonstrates the use of one or two safe working practices through photographic or written evidence.

It is up to the individual person to safeguard his or her health and safety in the work place. There are many different ways towards ensuring your safety. These include both ensuring you are wearing P.P.E (Personal Protective Equipment) this includes wearing: covered in shoes, safety glasses or goggles and earmuffs and also behaving maturely and correctly in the workplace, this is essential as accidents could occur in the workplace when not behaving correctly.

If you don't wear P.P.E (Personal Protective Equipment) when using machinery you are under risk of injuring yourself for example when you are using the router you need to wear eye protection for the chips getting flicked up and earmuffs for the noise.

